Form Approved: O.M.B. No. 2127-0008

U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository ☐
24-OCT-2006	Reference No. 10171756

OWNER INFORMATION (Type or Print)

Name [redacted]		Daytime Telephone Number [redacted]	E-mail Address [redacted]
Address [redacted]		Evening Telephone Number [redacted]	
City TOLEDO	**State** OH	**Zip Code** [redacted]	

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? ☒ *YES* ☐ *NO*
In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.
Signature of Owner _____ Date ___/___/___

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side	Make	Model	Model Year
JTHCK262265[redacted]	LEXUS	IS250	2006

Date Purchased	Dealer's Name and Telephone Number			Engine:	Fuel Type:
16-MAR-06	LEXUS OF TOLEDO 419-841-3500			No: Cylinders 6	Gas
Original Owner ☒	Dealer's City TOLEDO	State OH	Zip Code 43517		

Transmission Type		Powertrain	Vehicle Component Code
AUTOMATIC	☒ Antilock Brakes ☒ Cruise Control	ALL WHEEL DRIVE	180000 VEHICLE SPEED CONTROL Multiple Failure: 1

FAILED COMPONENT(S)/PART(S) INFORMATION

Incident Date(s)	Failure Mileage	Failure Speed
20-OCT-2006	5310	65

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:
Tire Component Code		Tire Failure Type

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash	Fire	Number of Persons Iniured	Number of Deaths	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No			Y

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

WIFE WAS DRIVING ON THE INTERSTATE WITH THE CRUISE ON DOING ABOUT 65 MPH, AND SHE DECIDED TO PASS A TRUCK. SHE ACCELLERATED SLIGHTLY, AND THE CAR SUDDENLY "FLOORED" TO OVER 90 MPH AND THE RPM'S WENT ALL THE WAY UP. SHE TRUNED OFF THE CRUISE, BUT IT WOULDN'T SLOW DOWN. SHE TRIED TO BRAKE, BUT THE ENGINE WAS STILL REVING AT THE HIGHEST SPEED. SHE FORCED HERSELF OFF INTO THE GRASSY MEDIAN AND SAT ON THE BRAKE UNTIL SHE COULD JAM THE TRANSMISSION INTO PARK AND TURN OFF THE ENGINE. VEH TOWED TO LEXUS DEALER. TECH COULDN'T FIGURE OUT WHAT WAS CAUSING THIS, BUT AFTER TALKING TO LEXUS HEADQUARTERS, THEY FOUND THAT THE RUBBER CAR MAT AND THE BACK OF THE ACCELLERATOR SOMEHOW CONNECTED AND FORCED THE CAR TO BE "FLOORED". YOU COULD NOT TELL BY LOOKING AT THE MAT THAT IT WAS CONNECTED TO THE ACCELLERATOR. MY WIFE WOULD OF DIED IF THERE HAD BEEN ANOTHER VEHICLE CLOSE TO HER. NO ACCIDENT OR INJURY. I HAVE NO COMPLAINT WITH THE DEALER. THEY DID EVERYTHING THEY COULD TO HELP. *NM

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a Manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.