National Automotive Sampling System



TIRE PRESSURE SPECIAL STUDY Update Tread Depth and Service Station Surveys

National Center for Statistics and Analysis

November 2001



References and Authors



 Based on two technical reports
 Tire Pressure Special Study-Tread Depth Analysis

 Kristin Thiriez and Rajesh Subramanian

 Air Pumps at U.S. Gas Stations: Major

 and Fees

Joseph Stevano

Survey Facts



Dates: Feb 1, 2001 through Feb 14, 2001


- Time: 8:00 am through 5:00 pm
- Data collected at NASS-CDS PSUs

Vehicle mix

- 6,442 passenger cars
- 1,874 sport utility vehicles
- 1,376 vans
- 1,838 pickup trucks

Sample Population





Tread Depth


Tread Depth Measurement








Tread Depth Distribution (each tire)



Tread Depth Cum Dist





---- Left Front Tire ----- Right Front Tire ----- Left Rear Tire ----- Right Rear Tire


Average Tread Depth



Left Fi	ront	8 .6
Right	Front	6.8
Left R	ear	7.0
Right	Rear	6.8


Minimum Measured Tread Depth





Inflation and Tread Depth





Tread Depth Findings



 Cars are being driven with minimal tread depths tires


 9 percent of passenger cars have at least one tire with 2/32" of tread depth or less
 Minimal tread depth tires are between 1.5

as tires with deeper tread.

Service Station Survey


Air Availability by Station Traffic Volume






Station Station Gauge Availability






Air Fees by Region





Station Gauge Accuracy






Over-Reporting by Station Gauges



Station Gauge	Percent over-reporting		
<u>Pressure (psi)</u>	<u>4 psi</u>	<u>6 psi</u>	<u>8 psi</u>
25	6	2	0
35	19	9	0
45	19	14	5
55	20	15	9

Hand Held Gauge Accuracy





Service Station Survey Findings



- U.S. gas station gauges tend to report a tire pressure which is higher than the actual pressure
 - nearly one gas station gauge out of five will over-report the tire pressure by 4 psi or more

 nearly one gas station gauge in 10 will overreport tire pressure by 6 psi or more
 Results in tires being under inflated!

Service Station Survey Findings (pg2)



Working available pumps - about 86%
Well over 90% of gas stations (having at least two islands) come equipped with air pumps
Nearly 10% of them will be out of order
Less than half of the pump-equipped gas stations also have a tire gauge

Further Information



 These research notes and other general information on highway traffic safety may be accessed by internet users at http://www.nhtsa.dot.gov/people/ncsa